



COMPONENTS



4" OCTAGONAL J-BOX REQUIRED FOR INSTALLATION



JUNCTION BOX (BY OTHERS)

INSTRUCTION KEY

INFORMATION

-  ADDITIONAL INSTALLATION SHOULD ONLY BE PERFORMED BY A CERTIFIED ELECTRICIAN
 -  ATTENTION REFER TO LOCAL/NATIONAL CODES FOR PROPER INSTALLATION
 -  POWER ON FAILURE TO FOLLOW INSTALLATION INSTRUCTION MAY VOID THE WARRANTY
 -  POWER OFF DO NOT TOUCH LEDS. LEDS MUST BE PROTECTED FROM MECHANICAL STRESS OR DEBRIS
- TURN OFF POWER DURING INSTALLATION OR SERVICING

1A

SET SCREWS

LOOSEN SET SCREWS TO REMOVE CEILING PLATE FROM CANOPY

1B

CEILING PLATE

2

JUNCTION BOX (BY OTHERS)

CEILING PLATE

SCREWS (BY OTHERS)

SET SCREW HOLES

i ENSURE CEILING PLATE IS ORIENTED AS SHOWN

3A

MAKE WIRING CONNECTIONS INSIDE JUNCTION BOX

3B

WIRING LEGEND

BLACK	HOT/LINE
WHITE	NEUTRAL
GREEN	GROUND
ORANGE	(DIM-)
PURPLE	(DIM+)

4A

SIDE VIEW

MOUNT CANOPY TO CEILING PLATE

4B





SIDE VIEW

4C



SET SCREWS

SECURE CANOPY TO CEILING PLATE WITH SET SCREWS

LED SERVICING



DRIVER SERVICING - DIRECT OR INDIRECT ONLY



DRIVER SERVICING - DIRECT/INDIRECT

