





6B




CANOPY IS SUITABLE FOR
MAXIMUM 3 CONDUIT FEEDS




1 CONDUIT FEED CANOPY



2




3




ENSURE CANOPY CLIPS ALIGN WITH BRACKET

4




CONNECT CANDUIT CANOPY AND FEED
JUNCTION BOX WIRES THROUGH HOLE

5



! CANOPY IS SUITABLE FOR
MAXIMUM 3 CONDUIT FEEDS

6 POWER CANOPY




WIRING LEGEND


BLACK	HOT/LINE
WHITE	NEUTRAL
GREEN	GROUND
ORANGE	(DIM-)
PINK	(DIM-)
BLUE	(DIM-)
PURPLE	(DIM+)
RED	(DIM+)

! MAKE WIRING CONNECTIONS

7




8




! CUT STEM LENGTH
IF APPLICABLE


9



10




11




 MAKE WIRING CONNECTIONS

12




13




DRIVER SERVICING

1




2




LED SERVICING


1



2




3




DRIVER SERVICING

1



2



3

